

PROJECT SOLUTIONS PTY LTD PO BOX 851 MITTAGONG NSW 2575

mob: 0416 156 962 info@projectsolutions.com.au www.projectsolutions.com.au

Established 2000.

Greenwich Hospital Redevelopment

Stage 1 - Early Works

DILAPIDATION REPORT



For TSA Riley Pty. Limited

10th September 2024

TSA Riley Pty. Limited Job No.: C1372

Project Solutions Job No: 25042

Development Application Number: SSD-13619238

Table of Contents

		Page
1.0	INTRODUCTION	3
2.0	SCOPE OF WORKS	4
3.0	SITE DESCRIPTION	4
4.0	OBSERVATIONS	7
5.0	CONCLUSIONS	11
	APPENDIX A – Site Plan	

APPENDIX B – Photographic Record of the Findings

1.0 INTRODUCTION

This report has been prepared from notes and photographic evidence obtained by a visual inspection of the below-mentioned areas. Project Solutions Pty. Limited has compiled the report acting on behalf of TSA Riley Pty. Limited.

The report aims to record the existing condition of the public and Hospital property deemed to be within a potential zone of influence prior to the commencement of works associated with the Stage 1 -early works of the Greenwich Hospital redevelopment.

The report has been compiled in accordance with condition C4 from the Development Application no. SSD-13619238.

In summary: -

Engaging Company: TSA Riley Pty. Limited

Contract Site: Greenwich Hospital – 95-115 River Road, Greenwich NSW 2065

Lots 3 and 4 DP584287

<u>Date of Survey</u>: 10th September 2024

<u>SSD Number:</u> <u>SSD-13619238</u>

- River Road Public domain area adjacent to the substation works.
- River Road Public domain area adjacent to the existing site access road.
- St Vincents Road Public domain area adjacent to the existing site access road.
- Boundary fence common with the residences along the western boundary (as seen from the site).
- Boundary fence common with the residences along the southern boundary (as seen from the site).
- Area of the existing roadway upgrade to the NW of 'Pallister'.
- Access road from River Road and St Vincents Road to the areas of work.

The particulars set out in this report are for the exclusive use of TSA Riley Pty. Limited. We accept no responsibility as a result of the use of this report by any other party. This report shall not be construed as a certificate or warranty of the areas surveyed. Refer to the disclaimer within the report.

2.0 SCOPE OF WORKS

The purpose of the report was to note and record the existing status of the public infrastructure, hospital property and other areas deemed to be within a potential zone of influence prior to the commencement of the stage 1 early works on the 'Greenwich Hospital Redevelopment'.

The Dilapidation Report shall be used amongst other means to assess the responsibility for any damage and / or making good arising out of the construction works to the areas listed above. The report is to provide a basis of discussion should it be alleged that the construction works has contributed to damage to any of the surveyed areas.

3.0 SITE DESCRIPTION

Greenwich Hospital is located at 95-115 River Road, Greenwich NSW 2065.

The redevelopment of the hospital will allow for the "Detail design, comprising the design, staged construction and operation of the hospital and integrated healthcare campus, including:-

- Hospital and aged care building (with integrates basement carpark);
- Two serviced seniors housing buildings (with integrated basement carpark);
- Respite care facility:
- Use of 'Pallister House' for research and administrative functions;
- Demolition works and remediation;
- Site facilities, services and infrastructure works;
- Pedestrian and vehicle access & circulation;
- Landscaping, including bushland regeneration; and signage".

Ref: Development application no. SSD-13619238

Note: this report is applicable to the Stage 1 early works component which will involve the following works:-

"Approvals

Contractor to finalise approvals (if not already achieved) for services including Sydney
Water (submit NOR and complete requirements to achieve s 73 certification),
Communications approvals, electrical ASP3 and ASP1 approvals, Jemena approvals,
stormwater connection approval through Lane Cove Council, and public domain road
works approvals and finalisation of FER.

Site Establishment and due diligence

- Contractor to allow for site establishment across relevant satellite sites on the Greenwich campus.
- Allow for relevant investigations and due diligence including pot holing, services diversions etc.
- Protection of existing services, trees and other items to be included.
- Ensure hospital remains operational throughout Early Works with a demonstrated staging plan to be endorsed by HammondCare.

Electrical

- Install temporary distribution board to back feed the existing Hospital and Riverglen Building. The board will be used as the main switchboard at the commencement of the main demolition works for stage 2.
- Install new electrical pit, sized to accommodate new incoming consumer mains.
- Temporary generator requirements and location to be further confirmed.

Communication

Install new temporary comms to the existing Hospital and Pallister House.

New Substation (2 New 1000KVA Kiosk Substation)

- Install new substation pad and retaining walls
- Install new pad mount transformers
- Install new screen with gate fronting River Road
- Decommission existing substation.

Water, Gas, and Sewer

- Divert existing water supply to Pallister House to enable proposed excavation for Stages 1
 & 2 from the existing hospital kitchen/plant area.
- Upgrade existing gas connection to the site
- Install new sewer connection for the future healthcare building adjacent Pallister House. New sewer to be travel under the stormwater pipe across the access road.
- Install new authority water main connection at the corner of River Road and St Vincents Road as per Section 73 Notice of Requirements.

Fire services

- Demolish existing single fire hydrant adjacent to Pallister House, and install new external dual fire hydrant, and extend the existing fire hydrant main pipework to feed.
- Provide a new fire brigade booster assembly with a large bore suction adjacent to the hospital building's vehicle entry ramp and facing River Road

Stormwater and civil enabling works

- Maintain access to the loading dock during the duration of the works
- Install new stormwater treatment pit, stormwater feed in point for the healthcare building, stormwater pits and connect into existing stormwater line.
- Construct perimeter berm on the southern boundary, refer to landscape plans for hedge plantings. The main objective for the berm is to support the hedge planting and provide privacy screening to the neighbours. Berm layout refer to landscape drawings.
- Proposed road realignment and tie into existing levels where relevant.
- Make good pavement on completion.
- Stormwater investigation and rectification for Pallister house (to be confirmed following site visit with HammondCare)

Landscaping

- Review VMP (travers plan) and TBLA landscape plan to ensure coordination, where discrepancies arise, raise the issue, and confirm direction for inclusion/exclusion.
- Construction of the nursery garden where the existing disused pool is has been included. Note: Design is being finalized, with consideration currently being reviewed to determine the most cost-effective construction methodology.
- Construction of southern berm to follow the approved landscape plans along the boundary.
- Inclusion of the restoration of planting to the APZ as per VMP.

Make Good and Site Handover

• Install wayfinding and statutory signage to support emergency services, visitors, staff, and residents".

Ref: TSA Riley email to Project Solutions dated 29th August 2024

The site's location can be seen in the following satellite image:-

Property Location

Red Dots indicated the location of the photographs taken recording the areas.



Ref: Houdah Geo

4.0 OBSERVATIONS

The main component of the report is the photographic and written evidence within appendix 'B' of this report.

The issued USB flash drive contains the following files: -

- o The photographic / written reports (PDF).
 - a. Also includes a 'Geotagged report' illustrating the approximate location of each photograph taken of the external areas.


- o The photographs used in the report (JPG's).
 - a. The Jpeg photographs on the USB flash drive are 36 mega-pixels to allow for greater resolution if a photo needs to be enlarged and viewed in greater clarity.


Note: the report should only be used to identify a particular photograph, which may require greater inspection. If a photo is required to be viewed in greater clarity, the relevant photograph/s can then be sourced on the issued USB flash drive and enlarged.

The photographs recording the external areas have been "Geotagged". To make use of this application, ensure that "Google Earth" has been installed on your computer. You will find the "Geotagged Report.kmz" file on the issued USB flash drive.

- 1. Open the ".kmz" file on the USB flash drive.
- 2. The application will launch in "Google Earth" (if installed on your computer).
- 3. You will note a series of numbered thumbnail photographs within and around the construction site. By clicking on a thumbnail photo the applicable photograph, taken in that approximate location will be revealed.

Note: this is an interactive file to be accessed on a computer via Google Earth and <u>not</u> from a visual interpretation of the screenshot/s of the 'Geotagged Report/s' on the following page/s.





The report does not allow for: -

- Faults to inaccessible parts of the adjoining properties / buildings.
- Faults concealed behind permanent wall cladding (i.e. timber paneling or floor coverings)
- Any testing.
- Arborist reporting.
- Geotechnical or subsurface investigations.
- ❖ Faults not apparent on a visual inspection.
- Faults apparent only in different environmental or weather conditions.
- ❖ Latent faults not apparent at the time of the inspection.
- ❖ Inspection of roof and sub floor voids or areas deemed dangerous to inspect.
- Pest inspection report.
- Inspection of Building services, plant and machinery.
- Requirements of the Building Code of Australia.
- ❖ Distribution of reports to parties other than our Client.

5.0 CONCLUSIONS

A record of the condition of the areas as of the 10th September 2024 has been presented. The findings are illustrated in the photographs bound within Appendix B of this report.

We suggest referring to the marked-up site plan within Appendix A of this report to reference which photographs record particular areas.

We also suggest using the "Find" operation in your PDF software to locate a particular room or named area.

The following items may be referred to should a need arise to review this report: -

- 1. Project North the cardinal compass points referenced within the report have been taken from the issued site plan.
- 2. The photographs illustrated in the 'geotagged report' are those which the camera had contact with the 'tagging satellite'. In some instances this contact can be lost through interference (electronic, magnetic, phone towers etc) and photos may not be tagged and illustrated within the report.
- 3. We suggest using the 'Geotagged Report' to source a photograph recording a particular area.

- 4. Besides using the 'Geotagged Report' to assist in the location of a particular photograph, we also suggest that you refer to the previous series of photographs in the report for the sequencing of recording areas.
- 5. Notable findings in the report include the following:
 - a. Cracked, crazed and damaged asphalt road paving and hardstand;
 - b. Cracked and damaged kerb and gutters;
 - c. Cracked and damaged concrete road paving;
 - d. Silted-up strip drains.
 - e. Dislodged stones and sandstone flagging to retaining structures;
 - f. Overgrown vegetation along the hospital boundaries;
 - g. Damaged boundary walls common with the properties along the southern side of the Hospital.
- 6. At the time of the inspection, it was noted that there were major civil works occurring to the 'Bob Campbell Oval' to the south of the Hospital.
- 7. The terrain along the hospital's western boundary was very steep and access to the area was difficult and some of the area was recoded from a distance.

In the best interest of all parties associated with this development a declaration for signing has been prepared on the following page.

SIGN-OFF SHEET

I / we believe that the written and photographic report is a true record of the existing condition of the following properties / areas as of the 10^{th} September 2024.

	l l
Areas Surveyed: Greenwich Hospital - internal access roads.	
River Road – Public domain – area a works.	djacent to the substation
River Road – Public domain – area adjacent to the existing site access road.	
St Vincents Road – Public domain – area adjacent to the existing site access road.	
Boundary fence common with the residences along the western boundary (as seen from the site).	
Boundary fence common with the residences along the southern boundary (as seen from the site).	
Area of the existing roadway upgrad 'Pallister'.	le to the NW of
Access road from River Road and St Vincents Road to the areas of work.	
	Date
	Date
	River Road – Public domain – area a works. River Road – Public domain – area a site access road. St Vincents Road – Public domain – existing site access road. Boundary fence common with the rewestern boundary (as seen from the southern boundary (as seen from the Area of the existing roadway upgrace 'Pallister'. Access road from River Road and St

We wish you every success with the development of this project. Thank you for choosing Project Solutions Pty. Limited to conduct your 'Dilapidation Reporting'. Please do not hesitate to contact the undersigned if you have any questions associated with the contents of this report.

The inspection and report compilation have been conducted by the undersigned who has a Bachelor of Building (UNSW 1993) and has been conducting construction reporting since 2000.

Yours faithfully,

Project Solutions Pty. Limited

Douglas Sandilands

Director

DISCLAIMER

Reports produced by Project Solutions Pty Ltd are prepared for a particular Client's objectives and are based on a specific scope, conditions and limitations, as agreed between Project Solutions and the Client. Information and / or report(s) prepared by Project Solutions may not be suitable for uses other than the original intended objective. No parties other than the Client should use any information and/or report(s) without first conferring with Project Solutions.

The information and/or reports prepared by Project Solutions should not be reproduced, presented or reviewed except in full. Before passing on to a third party any information and / or reports by Project Solutions, the Client is to fully inform the third party of the objective and scope and any limitations and conditions, including any other relevant information which applies to the material prepared by Project Solutions.


This survey and accompanying photographs is intended to present, as reasonably as possible, a record of the condition, by visible inspection only, of the aforementioned properties / areas.

The Client must also satisfy themselves that the report is accurate and contains no omissions. Project Solutions disclaims all responsibility for any loss whatsoever occasioned by any error in, or omission from this report.

Appendix A

Site Plan


Numbers illustrate the corresponding photograph numbers recording that particular area. Please also refer to the 'Geotagged Reports' for greater detail of which photographs record a particular area.



1:500 @ A1 THIS DRAWING IS IN COLOUR © COPYRIGHT THESE DRAWINGS AND DESIGNS AND THE COPYRIGHT THEREOF ARE THE PROPERTY OF BICKERTON MASTERS ARCHITECTURE PTY LTD (ACN 109 225 149) T/A BICKERTON MASTERS AND BM HEDE PTY LTD (ACN 630 149 996) T/A HEDE ARCHITECTS AND MUST NOT BE USED, RETAINED OR COPIED WITHOUT THE WRITTEN PERMISSION OF THE AFOREMENTIONED LEGAL ENTITIES.

BICKERTON MASTERS AND HEDE ARCHITECTS ACCEPT NO RESPONSIBILITY FOR THE USABILITY, COMPLETENESS OR ACCURACY OF DATA TRANSFERRED ELECTRONICALLY. RECIPIENTS SHOULD WHEN NECESSARY REQUEST A HARD COPY VERSION FOR VERIFICATION. USE FIGURED DIMENSIONS IN PREFERENCE TO SCALE. ALL DIMENSIONS TO BE VERIFIED ON SITE. IF THIS IS A COLOURED DRAWING AND IS PRINTED IN BLACK & WHITE NOT ALL INFORMATION MAY BE LEGIBLE.

P11 2024.06.07 STAGE 1 PRELIMINARY ISSUE NAH P10 | 2024.02.29 | CLIENT ISSUE ZB P9 2023.09.22 90% ISSUE NAH P8 2023.06.30 80% ISSUE NAH P7 | 2023.04.04 | STAGE 1 - 100% ISSUE NAH P6 2023.01.16 75% ISSUE TO ROBERTS CO. AMac **DETAILS** INITIALS REV DATE



NOT FOR CONSTRUCTION

PROJECT: 01605 **GREENWICH HOSPITAL** REDEVELOPMENT

RIVER RD, GREENWICH

SYDNEY

(02) 9261 8333

LEVEL 2, 231-233

COMMONWEALTH ST

SURRY HILLS 2010, NSW

www.bickertonmasters.com.au

Hammond Care
Champion Life

REVISION: AR-SW-0121 DATE: DRAWING TITLE:

STAGE 1 - EARLY WORKS SUMMARY

DRAWN: NAH **SCALE:** 1:500 @A1 CHECKED: NSW NOMINATED ARCHITECT: ANDREW MASTERS (9037) 7/06/2024 10:27:13 AM

NSW NOMINATED ARCHITECT: ANDREW MASTERS NSW ARB No. 9037

Appendix B

Photographic Record of the Findings



Greenwich Hospital Redevelopment. Refer to the following series of photographs for a record of the areas deemed to be within a zone of influence from the proposed 'Stage 1 – early works' as part of the Greenwich Hospital Redevelopment.



Greenwich Hospital Redevelopment. Refer to the following series of photographs for a record of the areas deemed to be within a zone of influence from the proposed 'Stage 1 – early works' as part of the Greenwich Hospital Redevelopment.

10/9/2024

PRO-0002.jpg

Hospital access from St Vincents Road. Power pole no. GL72349. Facing west from the eastern side of the road.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south. Damaged road and gutter.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south. Crossover to 18 St Vincents Road.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south. Crossover to 18 St Vincents Road.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south. Crossover to 18 St Vincents Road.



Hospital access from St Vincents Road. Area of power pole no. GL72349. Eastern side of the road. Heading south. Crossover to 18 St Vincents Road. Cracked shoulder of the layback.

Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area adjacent to 18 St Vincents Road.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area adjacent to 18 St Vincents Road.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area of the pedestrian crossing.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area of the pedestrian crossing.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area of the pedestrian crossing.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area of the pedestrian crossing. Crossover to the 20 St Vincents Road.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area of the pedestrian crossing.



Hospital access from St Vincents Road. Eastern side of the road. Heading south. Area adjacent to 20 St Vincents Road.

Hospital access from St Vincents Road. Eastern side of the road. Area on the southern side of the pedestrian crossing.



Hospital access from St Vincents Road. Western side of the road. Area on the southern side of the pedestrian crossing.

Hospital access from St Vincents Road. Western side of the road. Area on the southern side of the pedestrian crossing.



Hospital access from St Vincents Road. Western side of the road. Area of the pedestrian crossing.



Hospital access from St Vincents Road. Western side of the road. Area of the pedestrian crossing. Damaged fencing.



Hospital access from St Vincents Road. Western side of the road. Area of the pedestrian crossing. Damaged fencing.



Hospital access from St Vincents Road. Southern side of the intersection with the access road.



 $\label{thm:continuous} \mbox{Hospital access from St Vincents Road. Southern side of the intersection with the access road. Damaged fencing.}$



Hospital access from St Vincents Road. Southern side of the intersection with the access road. Hydrant Booster.



Hospital access from St Vincents Road. Southern side of the intersection with the access road. Hydrant Booster.



Hospital access from St Vincents Road. Intersection with the access road.



Hospital access from St Vincents Road. Intersection with the access road. Cracked paving.



Hospital access from St Vincents Road. Intersection with the access road. Cracked paving.



Hospital access from St Vincents Road. Intersection with the access road. Cracked paving.



Hospital access from St Vincents Road. Northern side of the intersection with the access road.



Hospital access from St Vincents Road. Northern side of the intersection with the access road. Damaged fencing. Area of power pole no. GL72349.



Hospital access from St Vincents Road. Northern side of the intersection with the access road. Area of power pole no. GL72349.



Hospital access from St Vincents Road. Northern side of the intersection with the access road. Area of power pole no. GL72349.



Hospital access from St Vincents Road. Northern side of the intersection with the access road. Power pole no. GL72349.



Hospital access from St Vincents Road. Northern side of the intersection with the access road. Power pole no. GL72349.

Hospital access from St Vincents Road. Northern side of the intersection with the access road. Power pole no. GL72349. Chipped kerb.



Hospital access from St Vincents Road. Intersection with the access road.



Hospital access from St Vincents Road. Intersection with the access road. Gouges in the road paving.



Hospital access from St Vincents Road. Intersection with the access road. Gouges in the road paving.



Hospital access from St Vincents Road. Intersection with the access road. Gouges in the road paving.



Hospital access from St Vincents Road. Intersection with the access road.



Hospital access from St Vincents Road. Intersection with the access road. Speed hump.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Area of the Hydrant Booster.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Gates.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.

Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.

PRO-0075.jpg



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Light pole.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Light pole and bollard.

PRO-0077.jpg



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Light pole and bollard.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Rock face on the northern side of the road.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Rock face on the northern side of the road.

Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Rock face on the northern side of the road.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Cracked paving.

PRO-0085.jpg



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Median strip.

Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Median strip.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Median strip.

Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House. Damaged PVC drain pipe.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.




Hospital access road from St Vincents Road. Heading west / uphill towards Pallister House.



Hospital access road from St Vincents Road. Area of Pallister House. Adjacent parking area. Damaged asphalt paving.



Hospital access road from St Vincents Road. Access / exit to Pallister House.



Hospital access road from St Vincents Road. Access / exit to Pallister House. Damaged kerb.



Hospital access road from St Vincents Road. Area of Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Area of Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Area of Pallister House. Cracked paving.



Hospital access road from St Vincents Road. Area of Pallister House. Damaged kerb.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west. Cracked paving.



Internal road adjacent to Pallister House. Heading west. Northern side of the road.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west. Light pole.


10/9/2024

PRO-0107.jpg



PRO-0108.jpg

Internal road adjacent to Pallister House. Heading west. Light pole.



Internal road adjacent to Pallister House. Heading west. Light pole.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west.



Internal road adjacent to Pallister House. Heading west. Damaged timber edging.

PRO-0117.jpg



Internal road adjacent to Pallister House. Heading south-west.



Internal road adjacent to Pallister House. Heading south-west.



Internal road adjacent to Pallister House. Heading south-west.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.

Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.

Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west. Strip drain.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west. Strip drain.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west. Strip drain.

PRO-0129.jpg



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west. Strip drain.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west.

PRO-0131.jpg



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west. Area of the speed bump.



Internal road between Pallister House and 'Ambulatory Services'. Heading south-west. Area of the speed bump.

PRO-0133.jpg



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Damaged road paving. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Damaged road paving. Area of proposed road works.




Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.




Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.

PRO-0139.jpg



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.




Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.




Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading south-west / downhill. Area of proposed road works.



Area to the west and below Pallister House. Parking bays.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.

PRO-0153.jpg



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.

PRO-0155.jpg



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Internal road between Pallister House and 'Health & Care'. Heading north-east / uphill. Area of proposed road works.



Area on the northern side of Pallister House. Heading south-west.



Area on the northern side of Pallister House. Adjacent car parking area. Damaged paving.



Area on the northern side of Pallister House. Adjacent car parking area. Damaged paving.

Area on the northern side of Pallister House. Adjacent car parking area. Damaged paving.



Area on the northern side of Pallister House. Adjacent car parking area. Damaged timber barricades.

PRO-0163.jpg



Area on the northern side of Pallister House. Adjacent car parking area. Timber barricades.



Area on the northern side of Pallister House. Adjacent car parking area. Timber barricades.



Area on the northern side of Pallister House. Adjacent car parking area. Timber barricades.



Area on the northern side of Pallister House. Adjacent car parking area. Steps leading down to the area of road works.



Area on the northern side of Pallister House. Adjacent car parking area. Steps leading down to the area of road works.



North-western side of Pallister House. Adjacent path and landscaping.

North-western side of Pallister House. Area of proposed road works. Facing northeast / uphill.



North-western side of Pallister House. Area of proposed road works. Facing northeast / uphill.

PRO-0171.jpg



North-western side of Pallister House. Area of proposed road works.



Greenwich Hospital access from River Road.

10/9/2024



Greenwich Hospital access from River Road. Area of the proposed substation works.



PRO-0173.jpg



PRO-0174.jpg

Greenwich Hospital access from River Road. Area of the proposed substation works.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Damaged kerb.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Lids to the services pits.

Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'.

Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Mail box.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Mail box.

Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Power pole no. GL72380.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Power pole no. GL72380.

Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading west. Area of the 'Sprinkler Booster'. Power pole no. GL72380.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster'. Power pole no. GL72380.

Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Damaged retaining wall.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Road paving.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Cracked and crazing road paving.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Cracked and crazing road paving.

Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Cracked and crazing road paving.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Cracked and crazing road paving.

PRO-0197.jpg



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Cracked and crazing road paving.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380.

PRO-0201.jpg



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380.



Hospital access from River Road. Area of the proposed substation works. Western side of the intersection. Heading east. Area of the 'Sprinkler Booster' and power pole no. GL72380. Damaged kerb.



Hospital access from River Road. Area of the proposed substation works. Heading east.



Hospital access from River Road. Area of the proposed substation works. Heading east.



Hospital access from River Road. Area of the proposed substation works. Heading east. Cracked road paving.



Hospital access from River Road. Area of the proposed substation works. Heading east. Cracked road paving.



Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading east. Footpath steps.



Hospital access from River Road. Area of the proposed substation works. Heading east. Footpath steps.



Hospital access from River Road. Area of the proposed substation works. Heading east. Footpath steps.



Hospital access from River Road. Area of the proposed substation works. Heading east. Footpath steps.



Hospital access from River Road. Area of the proposed substation works. Heading east. Nature strip.



Hospital access from River Road. Area of the proposed substation works. Heading east. Nature strip.



Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.




Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.


Hospital access from River Road. Area of the proposed substation works. Heading east. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading west. Footpath.



Hospital access from River Road. Area of the proposed substation works. Heading west. Footpath.




Hospital access from River Road. Area of the proposed substation works. Heading west. Footpath.

129



Hospital access from River Road. Area of the proposed substation works. Heading west. Footpath.



Hospital access from River Road. Area of the proposed substation works. Heading west. Footpath / steps.



Hospital access from River Road. Area of the proposed substation works. Heading west. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading west. Road paving.



Hospital access from River Road. Area of the proposed substation works. Heading west. Road paving.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road.

River Road. Area of the proposed substation works. Area on the eastern side of the internal access road.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the stone retaining wall.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the stone retaining wall.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the stone retaining wall.

PRO-0235.jpg



crazed state of the road paving.





PRO-0236.jpg

River Road. Area of the proposed substation works. Internal access road. Cracked and crazed state of the road paving.

River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Electrical kiosk no. 2385.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Existing electrical plant.

River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Stone retaining wall.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Stone retaining wall.

River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Stone retaining wall.




River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.

PRO-0243.jpg



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.

141



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.

River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Electrical kiosk.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping. (Bee hive in the tree hollow).



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.

River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Record of the landscaping.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Heading south.

PRO-0257.jpg




River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Heading south.



River Road. Area of the proposed substation works. Area on the eastern side of the internal access road. Damaged road paving.

River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road.

River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Signage and landscaping.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Cracked and crazed road paving.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Stone retaining wall.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Cracked and crazed road paving.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Cracked and crazed road paving.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Sediment on the road way.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Sediment on the road way.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Cracked paving.

River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Cracked paving.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Cracked paving.

PRO-0271.jpg



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Light pole and signage.



River Road. Area of the proposed substation works. Adjacent internal access road. Heading north towards River Road. Kerb and gutter.



River Road. Area of the proposed substation works. Adjacent internal access road. Kerb and gutter.



River Road. Area of the proposed substation works. Adjacent internal access road. Kerb and gutter.

River Road. Area of the proposed substation works. Adjacent internal access road. Kerb and gutter.



River Road. Area of the proposed substation works. Adjacent 'Sprinkler Booster' enclosure.

River Road. Area of the proposed substation works. Adjacent 'Sprinkler Booster' enclosure.



River Road. Area of the proposed substation works. Internal road. Heading south. Cracked and crazed road paving.

PRO-0279.jpg



River Road. Area of the proposed substation works. Internal road. Heading south. Silted up strip drain.



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.

Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.

PRO-0285.jpg



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.

PRO-0287.jpg



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.

10/9/2024



Internal access road from River Road. Heading south approaching the overhead walkway.

10/9/2024

PRO-0293.jpg



PRO-0294.jpg

Internal access road from River Road. Heading south approaching the overhead walkway.

PRO-0295.jpg



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.



PRO-0297.jpg



PRO-0298.jpg

Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.

PRO-0299.jpg



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.




Internal access road from River Road. Heading south approaching the overhead walkway.

PRO-0303.jpg



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south approaching the overhead walkway. Retaining wall.



Internal access road from River Road. Heading south approaching the overhead walkway. Western side of the road.

Internal access road from River Road. Heading south approaching the overhead walkway. Western side of the road. Damaged timber flagging.



Internal access road from River Road. Heading south approaching the overhead walkway. Western side of the road. Ramped building access.

PRO-0309.jpg




Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway.





PRO-0312.jpg

Internal access road from River Road. Heading south approaching the overhead walkway.

PRO-0313.jpg



Internal access road from River Road. Heading south approaching the overhead walkway.



Internal access road from River Road. Heading south approaching the overhead walkway. Damaged road paving.



Internal access road from River Road. Heading south - overhead walkway. Northern side.



Internal access road from River Road. Heading south - overhead walkway. Northern side.

PRO-0317.jpg



Internal access road from River Road. Heading south - overhead walkway. Retaining wall.



Internal access road from River Road. Heading south through the 'tunnel'. Damaged road paving.

PRO-0318.jpg

Internal access road from River Road. Heading south through the 'tunnel'. Damaged road paving.



Internal access road from River Road. Heading south through the 'tunnel'. Eastern side.



Internal access road from River Road. Heading south through the 'tunnel'. Western side.



Internal access road from River Road. Heading south through the 'tunnel'. Western side.



Internal access road from River Road. Heading south through the 'tunnel'.



Internal access road from River Road. Heading south through the 'tunnel'.



Internal access road from River Road. Heading south through the 'tunnel'.



Internal access road from River Road. Heading south through the 'tunnel'.



Internal access road from River Road. Heading south through the 'tunnel'.



Internal access road from River Road. Heading south through the 'tunnel'. Cracked paving.

Internal access road from River Road. Heading south. Area of 'Service and deliveries'.



Internal access road from River Road. Heading south. Area of 'Service and deliveries'.

Internal access road from River Road. Heading south. Area of 'Service and deliveries'.



Internal access road from River Road. Heading south. Area of 'Service and deliveries'. Collapsed section of the retaining structure.

Internal access road from River Road. Heading south. Area of 'Service and deliveries'. Retaining structure.



Internal access road from River Road. Heading south. Area of 'Service and deliveries'. Retaining structure.

Internal access road. Heading south. Area of 'Service and deliveries'. Retaining structure below the area of road works.



Internal access road. Heading south. Area of 'Service and deliveries'.

PRO-0337.jpg



Internal access road. Heading south. Area of 'Service and deliveries'.



Internal access road. Heading south. Area of 'Service and deliveries'. Retaining structure below the area of road works.

PRO-0339.jpg



Internal access road. Heading south. Area of 'Service and deliveries'.



Internal access road. Heading south. Area of 'Service and deliveries'.

PRO-0341.jpg



Internal access road. Heading south. Area of 'Service and deliveries'. Retaining structure below the area of road works. Damaged road paving.



Internal access road. Heading south. Area of 'Service and deliveries'. General record of the area.

PRO-0343.jpg



Internal access road. Heading south. Area of 'Service and deliveries'. General record of the area.



Internal access road. Heading south. Area of 'Service and deliveries'. General record of the area.

PRO-0345.jpg



Internal access road. Heading south. Area of 'Service and deliveries'. General record of the area.



Internal access road. Heading south. Area of 'Service and deliveries'. General record of the area.

Internal access road. Heading south. Area of 'Service and deliveries'. Area of the proposed road works.



Internal access road. Heading south. Area of 'Service and deliveries'. Area of the proposed road works.

PRO-0349.jpg



Internal access road. Heading south. Area of 'Service and deliveries'. Area of the proposed road works.



Internal access road. Heading south. Area of 'Service and deliveries'. Area of the proposed road works.

PRO-0351.jpg



Pallister House. North-western elevation. Area of the proposed road works.



Pallister House. North-western elevation. Area of the proposed road works.

10/9/2024



Pallister House. North-western elevation. Area of the proposed road works.

10/9/2024

PRO-0354.jpg

PRO-0353.jpg



Pallister House. North-western elevation. Area of the proposed road works.

Internal access road. Heading south. Area of 'Service and deliveries'. Area of the proposed road works.



Internal access road. Heading south. Area of 'Service and deliveries'. Area of the proposed road works.

Internal access road. Heading south. Area of 'Service and deliveries'.



Internal access road. Heading south. Area of 'Service and deliveries'.


Internal access road. Heading south. Area of 'Service and deliveries'.



Internal access road. Heading south. Area of 'Service and deliveries'. Lid to the services pit.



Internal access road. Area of 'Service and deliveries'. Heading west.



Internal access road. Area of 'Service and deliveries'. Heading west.

Southern property boundary. Area of the disused swimming pool.



Southern property boundary. Area of the disused swimming pool.



Southern property boundary. Area of the disused swimming pool.



Southern property boundary. Area of the disused swimming pool.



Southern property boundary. Area of the disused swimming pool.



Southern property boundary. Area of the disused swimming pool.





Southern property boundary. Area of the disused swimming pool. Collapsed boundary walls.



Southern property boundary. Area of the disused swimming pool. Collapsed boundary walls.



Southern property boundary. Area of the disused swimming pool. Breeze block boundary wall.



Southern property boundary. Area of the disused swimming pool. Breeze block boundary wall.



PRO-0373.jpg



PRO-0374.jpg

Southern property boundary. Area of the disused swimming pool. Adjacent tree.



Southern property boundary. Area of the disused swimming pool. Stone retaining wall.



Southern property boundary. Area of the disused swimming pool. Stone retaining wall.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Breeze block breeze block boundary wall to the unused swimming pool.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.

PRO-0383.jpg



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.

211



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.

214

Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 24 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.




Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.

PRO-0416.jpg

Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.




Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.




Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.

Southern property boundary. Heading east towards St Vincents Road. Common boundary with 53 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 55 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with $51\ \text{Gore}$ Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with $51\ \text{Gore}$ Street.

237



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51–47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51–47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51-47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51-47 Gore Street.

Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51–47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51–47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51--47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51-47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51--47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51--47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51--47 Gore Street.




Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51-47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51--47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51–47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 51-47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 47 Gore Street. Fallen tree limb.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 47 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Common boundary with 45 Gore Street.




Southern property boundary. Heading east towards St Vincents Road. Common boundary with 45 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Area of the common boundary with 43-35 Gore Street.



Southern property boundary. Heading east towards St Vincents Road. Area of the common boundary with 43-35 Gore Street.




Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 35 Gore Street.



Southern property boundary. Area of the common boundary with 37 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 37 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 37 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 37 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 39 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 41 Gore Street. Heading west.




Southern property boundary. Area of the common boundary with 41 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 41 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 41 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 41 Gore Street. Heading west.



Southern property boundary. Area of the common boundary with 41 Gore Street. Heading west.

Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged kerb.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Lean on the street sign.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

PRO-0500.jpg



Western side of the property. Internal access road. Heading north towards River Road.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

PRO-0502.jpg



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

PRO-0506.jpg



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.




Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

PRO-0512.jpg



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.




Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

PRO-0514.jpg



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.




Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.






Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.

Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road. Damaged road paving.



Western side of the property. Internal access road. Heading north towards River Road.



Western side of the property. Internal access road. Heading north towards River Road.

Western side of the property. Internal access road. Heading north towards River Road.



Western side of the property. Internal access road. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

PRO-0530.jpg




Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Strip drain.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Strip drain.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Strip drain.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Strip drain.

PRO-0542.jpg





Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Cracked paving.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Cracked paving.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

PRO-0554.jpg



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Structure above the undercover parking.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Structure above the undercover parking.

PRO-0556.jpg



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Structure above the undercover parking.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Cracked paving.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road. Cracked paving.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

PRO-0570.jpg





Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.




Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.


PRO-0578.jpg



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.

PRO-0582.jpg





Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Western side of the property. Internal access road on the western side of the hospital building. Heading north towards River Road.



Internal access road on the western side of the hospital building. Intersection with River Road.

Internal access road on the western side of the hospital building. Intersection with River Road.



Internal access road on the western side of the hospital building. Intersection with River Road.

Internal access road on the western side of the hospital building. Intersection with River Road.



Internal access road on the western side of the hospital building. Intersection with River Road. Cracked and crazed road paving.

Internal access road on the western side of the hospital building. Intersection with River Road. Cracked and crazed road paving.



Internal access road on the western side of the hospital building. Intersection with River Road. Cracked and crazed road paving.



Internal access road on the western side of the hospital building. Intersection with River Road. Cracked and crazed road paving.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.

Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.

Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Heading west.



Internal access road on the western side of the hospital building. Intersection with River Road. Record of the road paving.

PRO-0608.jpg



Internal access road on the western side of the hospital building. Intersection with River Road. Record of the road paving.



Internal access road on the western side of the hospital building. Intersection with River Road. Record of the road paving.

10/9/2024

PRO-0610.jpg



Internal access road on the western side of the hospital building. Western side of the intersection with River Road.



Internal access road on the western side of the hospital building. Western side of the intersection with River Road.

Internal access road on the western side of the hospital building. Western side of the intersection with River Road.



Internal access road on the western side of the hospital building. Western side of the intersection with River Road.



Internal access road on the western side of the hospital building. Western side of the intersection with River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.

PRO-0622.jpg



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.

10/9/2024



PRO-0628.jpg

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.

10/9/2024



PRO-0629.jpg

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117 River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.




Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.

PRO-0656.jpg

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.

PRO-0662.jpg



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.

Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road. Subsistence to the paving.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117B River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117A River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117A River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117A River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117A River Road.



Western hospital boundary. Heading south. Area adjacent to the common boundary with 117A River Road.



Western hospital boundary. Car park. Barricade and fence. Heading north.



Southern hospital boundary. Heading east towards the unused swimming pool.




Western hospital boundary.



Western hospital boundary.



Southern hospital boundary. Heading east towards the unused swimming pool.




South-western corner of the hospital boundary. Car park. Facing north-west.




South-western corner of the hospital boundary. Car park. Heading north-west.




South-western corner of the hospital boundary. Car park. Heading north-west.



South-western corner of the hospital boundary. Car park. Heading north-west.



South-western corner of the hospital boundary. Car park. Heading north-west.



South-western corner of the hospital boundary. Car park. Heading north-west.



South-western corner of the hospital boundary. Car park. Heading north-west.



South-western corner of the hospital boundary. Car park. Heading north-west.



South-western corner of the hospital boundary. Car park. Heading north-west.